

MONUMENT RECORD  
State of Indiana - County of Monroe

**Section:** 30

**Township:** 10 North

**Range:** 1 West


**Corner ID:** Wash C-19

**Monument Description & Remarks:** 5/8" Rebar with cap, "MUNDY L.S. 88014". Survey Sign 2ft above ground at pt. D

**References On File:** Legal Survey book 2, page 534 survey, Deputy Surveyor George Rader (1895), and Michael D. Mundy survey, Deck Property (2001), on file in Surveyor Office

RECOVERY TIE DRAWING  
Field Book 42 Page No. 17

farm  
field



- A - 5/8" Rebar with cap
- B - N 85° W 23.00' to MAG nail in 24" Red Oak
- C - N 07° E 14.71' to MAG nail in 6" Shagbark Hickory
- D - S 75° E 0.33' to 1/2" Rebar post

Not To Scale  
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 20th day of February, 2009.

*Kevin P. Enright*

Administered by the Monroe County Surveyor Review Board

Date: 3-10-2009

